

Press the <DIAL SEL> button and select [DIAL SHUTTER].

Press the <SHTR/F.RATE> dial.

and turn the <SHTR/F.RATE> dial to set the synchro scan.

Set the Shutter to 1/50